Dart Aerospace Ltd. Monday, 31/03/2008 1:44:43 PM User: 🕏 Jean-Luc Menard **Process Sheet** : WEARSHOE **Drawing Name** : CU-DAR001 Dart Helicopters Services Customer **Job Number** : 38253 **Estimate Number** : 12788 : D356413 **Part Number** P.O. Number : D3564 REVD **Drawing Number** : 31/03/2008 S.O. No. : This Issue : N/A **Project Number** Prsht Rev. : NC : D First Issue : // SMALL/MED FAB **Drawing Revision** : 38047 Material **Previous Run** 20 Um: : 07/04/2008 Qty: **Due Date** Written By Checked & Approved By New Issue 07-03-08 ec : Est Rev:A Comment As per Rev C 07-07-09 JLM Est Rev:B As per Rev D 07-09-09 JLM Verified By:EC Est Rev:C **Additional Product** Job Number: Description: Seq. #: **Machine Or Operation:** 304/316 .063 Sheet M304S16GA 1.0 0.2331 sf(s)/Unit Total: 4.6620 sf(s) Comment: Qty.: M304S16GA Stainless steel sheet 0.063" thick Batch: 107513 WATER JET FLOW WATER JET 2.0 Comment: FLOW WATER JET 1-Cut as per Dwg D3564 8-4-1 Dwg Rev: \(\begin{array}{c} \mu \end{array}\) Prog Rev: 1 2-Deburr if necessary 3.0 QC2 B 8-4-1 Comment: INSPECT PARTS AS THEY COME OFF MACHINE

QC8

SECOND CHECK

08/04/01 (33

Comment: SECOND CHECK

BRAKE NC


NC BRAKE



Comment: NC BRAKE

Deburr if necessary

Form on Brake as per Dwg D3564 using Jigs DT and DT % (



5.0

Each

Date: Monday, 31/03/2008 1:44:43 PM × Jean-Luc Menard User: **Process Sheet** Customer: CU-DAR001 Dart Helicopters Services **Drawing Name: WEARSHOE** Job Number: 38253 Part Number: D356413 Job Number: Seq. #: Description: **Machine Or Operation:** INSPECT WORK TO CURRENT STEP 6.0 QC5 **Comment: INSPECT WORK TO CURRENT STEP** Ensure joggle as per dwg D3429 POWDER COATING 7.0 **POWDER COATING** m 106442 **Comment: POWDER COATING** Powder Coat Grey Sandtex (Ref. 4.3.5.6) as per QSI 005 4.3 INSPECT POWDER COAT/CHEMICAL CONVERSION QC3 8.0 Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION PACKAGING RESOURCE #1 9.0 PACKAGING 1

Comment: PACKAGING RESOURCE #1

Identify and Stock

Location:

10.0


FINAL INSPECTION/W/O RELEASE


Comment: FINAL INSPECTION/W/O RELEASE


Job Completion



4/08/24/4







DART AEROSPACE LTD	Work Order:	38563	
Description: WEAR SHOE	Part Number:	D354-13	
Igspection Dwg: \\ \) \\ \\ \ \ \ \ \ \ \ \ \ \ \ \ \		Page 1 of 1	

FIRST ARTICLE INSPECTION CHECKLIST

X First Article Prototype

Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	
Ø .188	1:005001	, 191	*			
300 X300	7010	505X60E.	*			
7.00	7- 030	1.00	*			
766.8	t00	3.998	×			
2.432	1/ .010	2.435				
3,500	4 ,010	3.501	*			
			!	ļ	<u> </u>	
	:· .					<u> </u>
						·
			· · · · · · · · · · · · · · · · · · ·			
					ļ	
					·	
		· ·	-			
				-		
	-	·				
	-			-		
					· [· · · · · · · · · · · · · · · · · · ·

					<u> </u>	
Messured by:	HB	Audited by:	6,1	Prototype Approval:	1/	
Date:	8-4-1	Date:	08/04/6/	Date:	14	

Rev	Date	Change	 Revised by	Approved
A	· · · · · ·	New Issue	 CJ/JLM	

